



SERVICEMASTER 24/7

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999

Insured: JOHN ELLIOT
Property: 2035 COLORADO
GREENRIVER, WY

Claim Rep.: ROBERT RASMUSSEN
Business: 1175 W HWY 40
VERNAL, UT 84078

Business: (435) 828-2552

Estimator: ROBERT RASMUSSEN
Business: 1175 W HWY 40
VERNAL, UT 84078

Business: (435) 828-2552

Claim Number:

Policy Number:

Type of Loss:

Date of Loss: 12/11/2009
Date Inspected:

Date Received:
Date Entered: 12/23/2009 3:34 AM

Price List: WYRS4B8D
Restoration/Service/Remodel
Estimate: MOLD-ELLIOT

MOLD REMEDIATION EST. DUE TO OVER EXPOSER TO WATER FOR A EXTENDED PERIOD OF TIME.DUE TO
BROKEN PIPE IN STEAM HEATING SYSTEM



SERVICEMASTER 24/7

SERVICEMASTER 24/7
 1175 W. HWY. 40
 VERNAL, UT. 84078
 EMAIL-SERVICE@SMVERNAL.COM
 PHONE-435-789-2929, FAX-435-789-2999

MOLD-ELLIOT

MOLD-ELLIOT

DESCRIPTION	QNTY	UNIT COST	TOTAL
206. Contamination - air or surface testing & lab analysis	9.00 EA @	114.51 =	1,030.59

basement

Basement

Ceiling Height: 8'

DESCRIPTION	QNTY	UNIT COST	TOTAL
185. Seal/coat more than the ceiling - one coat (anti-microbial coating)	2,188.06 SF @	0.81 =	1,772.33
186. Negative air fan/Air scrubber (24 hr period) - No monit.	5.00 DA @	71.75 =	358.75
207. Neg. air fan/Air scrub.-Large (per 24 hr period)-No monit.	5.00 DA @	121.75 =	608.75

Main Level

mstr bed

Ceiling Height: 8'

DESCRIPTION	QNTY	UNIT COST	TOTAL
187. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	682.87 SF @	0.81 =	553.12

mstr-clst-2

Ceiling Height: 8'

DESCRIPTION	QNTY	UNIT COST	TOTAL
188. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	130.33 SF @	0.81 =	105.57

hall

Ceiling Height: 8'

Missing Wall: 1 - 3'6" X 8'0" Opens into living Goes to Floor/Ceiling

DESCRIPTION	QNTY	UNIT COST	TOTAL
189. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	393.50 SF @	0.81 =	318.74



SERVICEMASTER 24/7

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999

clst-4 **Ceiling Height: 8'**

DESCRIPTION	QNTY	UNIT COST	TOTAL
190. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	108.83 SF @	0.81 =	88.15

clst-2 **Ceiling Height: 8'**

DESCRIPTION	QNTY	UNIT COST	TOTAL
191. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	172.67 SF @	0.81 =	139.86

clst-3 **Ceiling Height: 8'**

DESCRIPTION	QNTY	UNIT COST	TOTAL
192. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	155.56 SF @	0.81 =	126.00

bed-3 **Ceiling Height: 8'**

DESCRIPTION	QNTY	UNIT COST	TOTAL
193. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	508.11 SF @	0.81 =	411.57

h-bath **Ceiling Height: 8'**

DESCRIPTION	QNTY	UNIT COST	TOTAL
194. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	319.50 SF @	0.81 =	258.80

bed-2 **Ceiling Height: 8'**



SERVICEMASTER 24/7

SERVICEMASTER 24/7
 1175 W. HWY. 40
 VERNAL, UT. 84078
 EMAIL-SERVICE@SMVERNAL.COM
 PHONE-435-789-2929, FAX-435-789-2999

DESCRIPTION	QNTY	UNIT COST	TOTAL
195. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	601.36 SF @	0.81 =	487.10

h-clst-2 **Ceiling Height: 8'**

DESCRIPTION	QNTY	UNIT COST	TOTAL
196. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	103.17 SF @	0.81 =	83.57

h-clst-1 **Ceiling Height: 8'**

DESCRIPTION	QNTY	UNIT COST	TOTAL
197. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	144.33 SF @	0.81 =	116.91

laundry **Ceiling Height: 8'**

Missing Wall: 1 - 2'1" X 6'8" Opens into kitchen Goes to Floor

DESCRIPTION	QNTY	UNIT COST	TOTAL
198. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	280.33 SF @	0.81 =	227.07

kitchen **Ceiling Height: 8'**

Missing Wall: 1 - 2'1" X 6'8" Opens into laundry Goes to Floor
 Missing Wall: 1 - 5'2" X 6'8" Opens into living Goes to Floor

DESCRIPTION	QNTY	UNIT COST	TOTAL
199. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	771.67 SF @	0.81 =	625.05



SERVICEMASTER 24/7

SERVICEMASTER 24/7
 1175 W. HWY. 40
 VERNAL, UT. 84078
 EMAIL-SERVICE@SMVERNAL.COM
 PHONE-435-789-2929, FAX-435-789-2999

living

Ceiling Height: 8'

Missing Wall: 1 - 3'9" X 8'0" Opens into entry Goes to Floor/Ceiling
 Missing Wall: 1 - 3'6" X 8'0" Opens into hall Goes to Floor/Ceiling
 Missing Wall: 1 - 5'2" X 6'8" Opens into kitchen Goes to Floor

DESCRIPTION	QNTY	UNIT COST	TOTAL
200. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	767.22 SF @	0.81 =	621.45
208. Negative air fan/Air scrubber (24 hr period) - No monit.	5.00 DA @	71.75 =	358.75

stairs-1

Ceiling Height: 17'

Missing Wall: 1 - 3'1" X 17'0" Opens into entry Goes to Floor/Ceiling

DESCRIPTION	QNTY	UNIT COST	TOTAL
201. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	194.43 SF @	0.81 =	157.49

landing

Ceiling Height: 8'

Missing Wall: 1 - 4'2" X 8'0" Opens into stairs-2 Goes to Floor/Ceiling

DESCRIPTION	QNTY	UNIT COST	TOTAL
202. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	118.08 SF @	0.81 =	95.64

stairs-2

Ceiling Height: 17'

Missing Wall: 1 - 4'2" X 17'0" Opens into landing Goes to Floor/Ceiling

DESCRIPTION	QNTY	UNIT COST	TOTAL
203. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	232.62 SF @	0.81 =	188.42

entry

Ceiling Height: 8'

Missing Wall: 1 - 3'1" X 8'0" Opens into stairs-1 Goes to Floor/Ceiling



SERVICEMASTER 24/7

SERVICEMASTER 24/7
 1175 W. HWY. 40
 VERNAL, UT. 84078
 EMAIL-SERVICE@SMVERNAL.COM
 PHONE-435-789-2929, FAX-435-789-2999

Missing Wall: 1 - 3'9" X 8'0" Opens into living Goes to Floor/Ceiling

DESCRIPTION	QNTY	UNIT COST	TOTAL
204. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	80.38 SF @	0.81 =	65.11

mstr-clst-1 Ceiling Height: 8'

DESCRIPTION	QNTY	UNIT COST	TOTAL
205. Seal/coat more than the walls and ceiling - one coat (anti-microbial coating)	128.67 SF @	0.81 =	104.22

Adjustments for Base Service Charges Adjustment

Painter			95.50
Total Adjustments for Base Service Charges:			95.50

Line Item Totals: MOLD-ELLIOT 8,998.51

Grand Total Areas:

5,809.42 SF Walls	2,606.54 SF Ceiling	8,415.96 SF Walls and Ceiling
2,675.13 SF Floor	297.24 SY Flooring	726.58 LF Floor Perimeter
0.00 SF Long Wall	0.00 SF Short Wall	726.17 LF Ceil. Perimeter
2,675.13 Floor Area	2,782.38 Total Area	5,374.67 Interior Wall Area
2,523.33 Exterior Wall Area	315.42 Exterior Perimeter of Walls	
0.00 Surface Area	0.00 Number of Squares	0.00 Total Perimeter Length
0.00 Total Ridge Length	0.00 Total Hip Length	



SERVICEMASTER 24/7

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999

Summary for Dwelling

Line Item Total				8,903.01
Total Adjustments for Base Service Charges				95.50
Material Sales Tax	@	6.000%	x	4,301.48
				258.09
Replacement Cost Value				\$9,256.60
Net Claim				\$9,256.60

ROBERT RASMUSSEN



SERVICEMASTER 24/7

SERVICEMASTER 24/7
 1175 W. HWY. 40
 VERNAL, UT. 84078
 EMAIL-SERVICE@SMVERNAL.COM
 PHONE-435-789-2929, FAX-435-789-2999

Recap by Room

Estimate: MOLD-ELLIOT	1,030.59	11.45%
Area: basement		
Basement	2,739.83	30.45%
<hr/>		
Area Subtotal: basement	2,739.83	30.45%
Area: Main Level		
mstr bed	553.12	6.15%
mstr-clst-2	105.57	1.17%
hall	318.74	3.54%
clst-4	88.15	0.98%
clst-2	139.86	1.55%
clst-3	126.00	1.40%
bed-3	411.57	4.57%
h-bath	258.80	2.88%
bed-2	487.10	5.41%
h-clst-2	83.57	0.93%
h-clst-1	116.91	1.30%
laundry	227.07	2.52%
kitchen	625.05	6.95%
living	980.20	10.89%
stairs-1	157.49	1.75%
landing	95.64	1.06%
stairs-2	188.42	2.09%
entry	65.11	0.72%
mstr-clst-1	104.22	1.16%
<hr/>		
Area Subtotal: Main Level	5,132.59	57.04%
<hr/>		
Subtotal of Areas	8,903.01	98.94%
Base Service Charges	95.50	1.06%
<hr/>		
Total	8,998.51	100.00%



SERVICEMASTER 24/7

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999

Recap by Category

Items	Total Dollars	%
PAINTING	6,546.17	70.72%
WATER EXTRACTION & REMEDIATION	2,356.84	25.46%
Subtotal	8,903.01	96.18%
Base Service Charges	95.50	1.03%
Material Sales Tax @ 6.000%	258.09	2.79%
Total	9,256.60	100.00%



SERVICEMASTER 24/7

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



1 007 12/19/2009
Taken By: SUPER



SERVICEMASTER 24/7

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



2 008 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



3 009 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



4 010 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



5 011 12/19/2009
Taken By: SUPER



SERVICEMASTER 24/7

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



6 012 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



7 013 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



8 014 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



9 015 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



10 016 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



11 017

12/19/2009

Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



12 018 12/19/2009
Taken By: SUPER



SERVICEMASTER 24/7

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



13 019 12/19/2009
Taken By: SUPER



SERVICEMASTER 24/7

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



14 020 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



15 021 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



16 022

12/19/2009

Taken By: SUPER



SERVICEMASTER 24/7

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



17 023 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



18 024 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



19 025 12/19/2009
Taken By: SUPER



SERVICEMASTER 24/7

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



20 026

12/19/2009

Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



21 027

12/19/2009

Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



22 028

12/19/2009

Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



23 029

12/19/2009

Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



24 030

12/19/2009

Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



25 031 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



26 032

12/19/2009

Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



27 033 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



28 034 12/19/2009
Taken By: SUPER



SERVICEMASTER 24/7

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



29 035 12/19/2009
Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



30 036

12/19/2009

Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



31 037

12/19/2009

Taken By: SUPER

SERVICEMASTER 24/7
1175 W. HWY. 40
VERNAL, UT. 84078
EMAIL-SERVICE@SMVERNAL.COM
PHONE-435-789-2929, FAX-435-789-2999



32 038

12/19/2009

Taken By: SUPER

large capacity 2200 cfm neg-air



